

Scan Victory	XTO Energy	Blazek-Spring Branch -Louis Cook 1H	Spudded: 3/26/2019	Richard Tucker	J. Eric Blake
281-605-2120	N 31 25 18 W -96 11 12			Freestone, Co	(Ark-La-Tex)
From Jewett take Division Rd. North about 4 miles, turn left onto lease road and go about 2 miles to location.					
Scan Discoverer	Diamondback Energy	Neal/Leathco 34-33 B Unit 11WB	Spudded:	Travis Richardson	Corey Boyd
281-605-2121	N 31 36 23 W -103 39 59			Reeves, Co	(Permian-Basin)
Take I-20 to Exit 80. Turn South on TX Hwy 18 and continue South for 6.4 miles. Turn right on to TX Hwy 1776 and continue South for 17.3 miles to TX Hwy 1450. Turn right for 0.4 miles to TX Hwy 1776. Turn left on TX Hwy 1776 and continue South for 14.8m, turn left on to lease (Gate C) and continue 3.3 miles to Y, stay Right at Y, continue 3.2 miles to location on right.					
Scan Pride	Waterfield Midstream	Capri 1 SWD	Spudded: 4/19/2019	Keith Davis	Mitchell Clemens
281-605-2123	N 1 0 0 W -1 0 0			Martin, Co.	(Permian-Basin)
From Texas 250 Loop & 349 go North on TX -349 for about 24.4 miles to Holt Ranch Road, take a right and go East about 1 mile (from old location go South on 349 about 3.5 miles turn left on Holt Ranch Road)					
Scan Producer	XTO Energy	ST. Kitts 76 2833 2H	Spudded: 4/18/2019	Shawn Mills	Wesley McDonald
281-605-2126	N 31 56 31 W -103 33 9			Loving, Co.	(Permian-Basin)
FROM INTERSECTION OF HWY 302 AND FM 1933 GO NORTH ON FM 1933 (ROAD TURNS INTO CR 300) GO 15.5 MILES, TURN RIGHT (ROSE HILL RANCH) CROSS CATTLE GAURD STAY LEFT AND GO 1.7 MILES, TURN RIGHT AND GO 4.9 MILES, TURN RIGHT AND GO 2 MILES, TURN RIGHT THEN LEFT AND GO 4 MILES, TURN RIGHT AND GO .9 MILE STAY STRAIGHT FOR ANOTHER .8 MILE, TURN RIGHT AND FOLLOW TO RIG. (THERE IS A RIG SIGN AR EVERY TURN)					
Scan Spirit				Clifton Belyeu	Charles Nichols
281-605-2129	N 000 W -000	Waiting on next location		Harrison, Co.	(Ark-La-Tex)
INTERSECTION I-20& US 59 SOUTH 4.1MILES TO CR 2625 TURNRIGHT ON 2625 GO 3.1 MILEST CR 3041TRUN LEFT GO 1.8 MILES TO KEY FARM RD TURN LEFTGO .25 MILES THROUGH GATEON LEFT FOLLOW LEASE ROAD TO RIG					
Scan Cross	Tanos, LLC	Beckham -Mauritzen-Vera Davis 1H	Spudded: 4/22/2019	Andrew Crump	Barry Staland
281-605-2130	N 32 7 47 W - 94 51 18			Panola, Co.	(Ark-La-Tex)
From the intersection of SW loop 436 in Carthage & SH 315, go towards and through Clayton, TX. for about 9.3 mile. Turn left onto lease road and travel .5 miles to rig.					
Scan Gold	XTO Energy	CASSIDY UNIT 2 3078JH	Spudded: 4/3/2019	J. Monty Shultz	Dustin Smith
281-605-2131	N 32 16 1 W -101 47 12			Martin, Co.	(Permian-Basin)
NORTH OF STANTON FROM INTERSECTION OF HWY 176 & 137 GO EAST ON 176 FOR 5.7 MILES TURN LEFT ON CR 3901 FOR ABOUT .8 MILES, TURN LEFT ON LEASE RD. GO ABOUT .3 MILES AND TURN RIGHT TO LOCATION.					
Scan Freedom (NM)	COG Operating, LLC	Daisy 24 State Com 503H	Spudded: 4/25/2019	Josh Miller	Reggie Murray
281-605-2132	N 32 7 18 W -104 8 45			Eddy, Co.	(Permian-Basin)
Starting South of Malaga, NM on Hwy 285 go South, 9.1 miles (mile marker 9) turn right (West) on lease road, go about 3.4 miles, turn left (South) go about .1 mile to location.					
Scan Texas	Diamondback Energy	Benton 3-12 601H	Spudded: 3/26/2019	Jon Bruce Trotter	Rocky Broumley
281-605-2133	N 31 36 55 W -103 33 11			Reeves, Co	(Permian-Basin)
FROM THE INTERSECTION OF I-20 AND 285 EXIT 42 TAKE 285 NORTH FOR 8.4 MILES TO CR 424. TURN RIGHT ON CR 424 AND GO 1.6 MILES TO FM 1216 TURN LEFT ON FM 1216 AND GO 7.3 MILES TO THE LEASE GATE ON THE LEFT TURN LEFT THROUGH THE GATE AND GO 0.4 MILES TURN LEFT AND GO 0.2 MILES TO LOCATION.					
Scan Patriot	Rio Oil & Gas (Permian) II,LLC	Conquista State Unit 54-1-8 9H	Spudded: 5/11/2019	John Carroll	Justin Shirey
281-605-2134	N 31 25 21 W -103 31 24			Reeves, Co.	(Permian-Basin)
From the intersection on 302 and 285. Turn left (south) on 285 for 0.6 miles. Turn right (west) onto lease road for 1.1 miles and the location will be on the left.					
Scan Liberty	Castleton Resources	SN1 AGC 1HH	Spudded: 3/18/2019	James Manderud	Paxton Lindsey
281-605-2135	N 32 10 26 W -94 11 44			Panola, Co	(Ark-La-Tex)
From the loop in Carthage, TX take HWY 79 North for 7.3-miles. Turn right onto FM. 123 and head East for 2.7-miles. Turn right on HWY 31 and drive South for 3.5-miles Turn right onto County Road 447 drive West thru gate about 0.2miles. to PR road847 about 0.4 miles, follow white rock lease road into C.C.I. Alexander unit 01-06 (stay on lease road) total of 1.8 miles from Hwy 31(staging rig while waiting on separate location)					
Scan Star	Diamondback Energy	State Barb 10-5 B 2WA	Spudded : 5/6/2019	Randy Joseph	Wayne Fitzgerald
281-605-2136	N 31 19 45 W - 103 13 13			Reeves, Co.	(Permian-Basin)
FROM THE INTERSECTION OF I-20 & HWY 18 (EXIT 80) IN MONAHANS TX, GO SOUTH ON HWY 18 FOR 4.6 MILES. TURN RIGHT ONTO FM 1776 AND CONTINUE SOUTHWEST FOR 17.3 MILES TO FM 1450. GO NORTHWEST TOWARDS PECOS ON FM 1450 FOR 10.3 MILES TO LEASE ROAD ON RIGHT. TURN ONTO LEASE ROAD AND CONTINUE FOR 0.3 MILES. TURN RIGHT AND GO 0.1 MILES TO PAD ON LEFT.					
Scan Endeavor	XTO Energy	Penguins DU H1	Spudded: 5/6/2019	Kenny Fickey	Kyle Sutton
281-605-2139	N 31 26 5 W -94 15 50			San Augustine, Co.	(Ark-La-Tex)
FROM SAN AUGUSTINE, AT INTERSECTION OF HWY 96 & HWY 1277, GO SOUTH ON 1277 APPROXIMATELY 10 MILES TO LEASEROAD ON LEFT. TURN AND FOLLOW TO RIG FROM INTERSECTION OF HWY 103 & 1277 (AT CROSSROADS) GO NORTH ON 1277 FOR 5 MILES TO LEASE ROAD ON RIGHT.TURN AND FOLLOW TO RIG.					
Scan Vision	XTO Energy.	Zant Bridget 2605 2625SH	Spudded:	Lance Dement	Justin Molandes
281-605-2140	N 32 22 12 W -101 49 48			Martin, Co.	(Permian-Basin)
FROM INTERSECTION OF I-20 AND 137 IN STANTON. GO SOUTH ON 137 FOR 12 MILES. TURN LEFT ONTO CR 460, GO 0.4 MILES TO LOCATION					
Scan Quest (NM)	COG Operating, LLC	Boone 16 State Com 4H	Spudded:	Tony Richardson	Zach Collett
281-605-2141	N 32 28 31 W -103 35 0			Lea,Co.	(Permian-Basin)
From the Intersection of 62/180 and Hwy 176, go Southwest on Hwy 176 about 14.7 miles. Turn right (Southwest) onto lease road, go about 3.7 miles to right turn west go about 4.2 miles. Turn right (Northwest) go about 1 mile to right turn (North) go about 1.3 miles stay left at fork. Turn right (East) go about 1.8 miles to location on south side of road.					
Scan Titan	KJ Energy	Todd 2H	Spudded: 3/7/2019	Dewayne Harris	Wise Menah
281-605-2137	N 32 4 51 W -94 34 35			Rusk. Co	(Ark-La-Tex)
FROM HENDERSON TEXAS TAKE 79 EAST TOWARD CARTHAGE FOR ABOUT 12.2 MILES AND TURN RIGHT ON FM 1798. GO ABOUT 3 MILES TO 348. TURN LEFT, GO ABOUT 2 MILES, LOOK FOR LEASE RD. ON RIGHT. TURN INTO LEASE RD.. GO ABOUT 0.5 MILE TO LOCATION ON RIGHT.					

Odessa New Yard address: 551 South FM 866, Odessa, TX 79763. Office # 432-332-8084

(From Odessa head west On I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles, yard on East side (right).

Rig Manager on duty is **Highlighted**