

Scan Discoverer	DE3 OPERATING, LLC	JAVOID WEST A 40-45 2801H	Spudded: 10/20/20	Travis Ball	Truitt Thompson
281-746-9653	N 32.052188 W -101.921310			Midland, CO	(Permian Basin)
From 1-20 in Midland -take HWY 307 East towards Greenwood for 6.1 Miles. Turn North (Left) on to CR 1090 & drive 2 miles. Turn East (Right) on to lease Rd. Rig will be the first location on the right. NEXT RIG MOVE: Walk forward 25' to next well.					
Scan Spirit	Sabine Oil and Gas	STRONG CRIM 1-H-3	Spudded: 8/21/20	James Manderud	Charles Nichols
281-606-2279	N 32.17190 W -94.79742			RUSK, CO.	(Ark-La-Tex)
FROM HWY 79 & LOOP 571 GO 5.1 MILE TURN RIGHT ON TO CR.203 GO 1 MILE TURN ONTO INDUSTRIAL, GO .5 MILE TURN LEFT ONTO LEASE ROAD GO .5 MILES TO LOCATION. NEXT RIG MOVE: IN HENDERSON TEXAS FROM INTERSECTION OF HWY 79 AND 259 GO SOUTH 3.5 MILES TURN LEFT ON COUNTY RD 317 GO 2.5 MILES TO LEASE RD ON RIGHT GO .5 MILES TO LOCATION.					
Scan Patriot	Chisholm Energy	BUFFALO 12-1 FED COM 2 BS #4	Spudded: 10/18/20	Joseph Dover	Justin Shirey
903-205-8399	N 32.6681 W -103.6125			LEA, CO	(NM)
FROM HOBBS, NM TAKE 180 WEST FOR 30 MILES. TURN RIGHT ON SMITH RANCH ROAD. GO 2 MILES, TURN RIGHT ON LEASE ROAD (BY BIG CIMAREX SIGN). GO 2 MILES- TAKE A LEFT. GO 1.9 MILES- STAY TO LEFT. GO 8/10ths OF A MILE ONTO LOCATION. NEXT RIG MOVE INFO: Walk forward.					
Scan Star	3 Bear Field Services	Doodle Bug State SWD #1	Spudded:	Mitchell Clemens	Jeramie Dickens
281-742-0874	N W			LEA, CO.	(Permian-Basin)
MOVING TO LOCATION: 10/24/20 From Jal, NM- head west on hwy 128 for 19.7 miles. Turn right on Delaware Basin road. Head north for 5.8 miles. Turn left on lease road at Targa Midstream sign (red pipe entrance). Go west for 2.4 miles. Turn right (north) go 8 miles. Turn left on location road for 100 yards. NEXT RIG MOVE INFO: TBA					
Scan Quest	Concho	Snap Back FED COM 702H	Spudded: 9/19/20	Tony Richardson	Keith Davis
281-766-7242	N 32.1959 W -103.413			LEA, CO. (NM)	(Permian Basin)
TAKE HWY 128 FROM JAL WEST FOR 17 MILES (MILE MARKER 39) TURN RIGHT INTO LEASE ROAD GO 0.8MILES TURN LEFT GO 0.9 MILES TO RIG NEXT RIG MOVE INFO: From the intersection of HWY 302 and HWY 115- in Kermit, TX take HWY 302 West for 20 miles (MM 200.7). Turn right and go 7.8 miles. Turn left and g 0.1 mile to the location.					
Scan Legacy	XTO ENERGY	Mobley 1-21H28X33	Spudded: 07/28/20	Chuck High	Derek Yarbrough
281-606-0182	N 34.0269 W -97.3173			LOVE, CO.	(OKLAHOMA)
From Marietta, OK- TRAVEL NORTH ON I-35 TO ARDMORE TAKE EXIT 21 – OSWALT RD. GO LEFT – WEST ON OSWALT RD, UNDER I-35 OVERPASS FOR 10 MILES TO LOCATION ON LEFT.					
Odessa Yard	Office # (432) 332-8084				
551 South FM 866, Odessa, TX 79763. From Odessa head west On I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles, yard on East side (right).					
Yukon Yard	Office # (405) 437-0408				

Rig Manager on duty is **Highlighted**