

Scan Victory	XTO Energy	Spring Branch-Louis Cook 1H	Spudded: 4/30/2019	Richard Tucker	J. Eric Blake
281-605-2120	N 31 25 19 W -96 11 13			Freestone, Co	(Ark-La-Tex)
FROM INTERSECTION OF HWY 79 AND DIVISION ST IN JEWETT, GO WEST ON DIVISION FOR 4 MILES. TURN LEFT ONTO LOCATION ROAD. FOLLOW LOCATION ROAD 2 MILES TO RIG					
Scan Discoverer	Diamondback Energy	Neal/Leathco 34-33 B Unit 11WB	Spudded: 5/19/2019	Travis Richardson	Corey Boyd
281-605-2121	N 31 14 34 W -103 3 52	Rig Move		Reeves, Co	(Permian-Basin)
FROM INTERSECTION OF I-20 AND SH-18, Take I-20 to Exit 80. Turn South on TX Hwy 18 and continue South for 6.4 miles. Turn right on to TX Hwy 1776 and continue South for 17.3 miles to TX Hwy 1450. Turn right for 0.4 miles to TX Hwy 1776. Turn left on TX Hwy 1776 and continue South for 14.8m, turn left on to lease (Gate C) and continue 3.3 miles to Y, stay Right at Y, continue 3.2 miles to location on right. Next Location: FROM INTERSECTION OF I-20 AND SH-18, Take I-20 to Exit 80. Turn South on TX Hwy 18 and continue 35 miles to Lethco Lane(large steelgate entrance). Turn right on Lethco Lane and travel 4.6 miles, turn right thru yellow cattle guard and travel 2 miles, turn left and travel .5 miles, turn left and travel .1 miles, turn right by frac pit and travel .6 miles to location entrance on left.					
Scan Pride	Waterfield Midstream	Corfu SWD 1	Spudded: 6/4/2019	Keith Davis	Mitchell Clemens
832-665-2251	N 32 17 21 W -101 52 17			Martin, Co.	(Permian-Basin)
FROM THE INTERSECTION OF 137 AND 176 NORTH OF STANTON, GO WEST ON 176 FOR 1.1 MILES, TURN SOUTH ON CR3301, GO 1 MILE, TURN LEFT (EAST) GO 1/2 MILE TO LOCATION. FROM OLD LOCATION GO SOUTH ON 349 FOR 4 MILES, TURN LEFT ON 176 FOR 25 MILES, TURN RIGHT ON CR3301 (RIGHT NEXT TO LENORAH POST OFFICE) GO 1 MILE, TURN LEFT ON LEASE ROAD, FOLLOW 1/2 MILE TO RIG.					
Scan Producer	XTO Energy	ST. Kitts 76 2833 2H	Spudded: 4/18/2019	Shawn Mills	Wesley McDonald
432-281-4941	N 31 56 31 W -103 33 9			Loving, Co.	(Permian-Basin)
FROM INTERSECTION OF HWY 302 AND FM 1933 IN MENTONE TX: GO NORTH ON FM 1933 (ROAD TURNS INTO CR 300) GO 15.5 MILES, TURN RIGHT (ROSE HILL RANCH) CROSS CATTLE GAURD STAY LEFT AND GO 1.7 MILES, TURN RIGHT AND GO 4.9 MILES, TURN RIGHT AND GO 2 MILES, TURN RIGHT THEN LEFT AND GO 4 MILES, TURN RIGHT AND GO .9 MILE STAY STRAIGHT FOR ANOTHER .8 MILE, TURN RIGHT AND FOLLOW TO RIG. (THERE IS A RIG SIGN At EVERY TURN)					
Scan Spirit	Tanos, LLC	Apliston Alt 1&2	Spudded:	Clifton Belyeu	Charles Nichols
281-605-2129	N 000 W -000	Waiting on next location / Rig Move		Harrison, Co.	(Ark-La-Tex)
INTERSECTION I-20& US 59 SOUTH 4.1MILES TO CR 2625 TURNRIGHT ON 2625 GO 3.1 MILEST CR 3041TRUN LEFT GO 1.8 MILES TO KEY FARM RD TURN LEFTGO .25 MILES THROUGH GATEON LEFT FOLLOW LEASE ROAD TO RIG. Next Location: FROM I-20 IN MARSHALL TAKE US 59 SOUTH 7.2 MILES. TURN LEFT ON FM 1186 GO 6.9 MILES TO HORTON. TURN LEFT ON FM 1186 AND FM 1794 GO 1.8 MILES TURN LEFT ON CO.RD 311. GO 1.5 MILES TURN RIGHT ON ENTRANCE TO LOCATION.					
Scan Cross	Tanos, LLC	Jenkins East-Doyh Mekh	Spudded: 5/31/2019	Andrew Crump	Barry Stanaland
281-605-2130	N 32 24 50 W -94 22 51			Harrison, Co.	(Ark-La-Tex)
From South of Marshall,Tx : At the intersection of I-20 & US 59 take US 59 south 4.1 miles to CR 2625. Turn right on CR 2625 and go .9 miles to Key Farm Road. Turn left and go 1.6 miles to Tom Daniels Road. Turn right and go .3 miles.Turn right on lease road and follow to rig.					
Scan Gold	XTO Energy	CASSIDY UNIT 2 3006DH	Spudded: 6/3/2019	J. Monty Shultz	Dustin Smith
281-605-2131	N 32 17 39 W -101 46 24			Martin, Co.	(Permian-Basin)
NORTH OF STANTON FROM INTERSECTION OF HWY 176 & 137 GO EAST ON 176 FOR 5.7 MILES TURN LEFT ON CR 3901 FOR ABOUT .8 MILES, TURN LEFT ON LEASE RD. GO ABOUT .3 MILES AND TURN RIGHT TO LOCATION.					
Scan Freedom (NM)	COG Operating, LLC	Howitzer Federal Com 606H	Spudded: 6/7/2019	Josh Miller	Reggie Murray
281-605-2132	N 32 14 0 W -104 1 57			Eddy, Co.	(Permian-Basin)
FROM ORLA, TX TAKE 285 NORTH TO MALAGA, NM. TURN RIGHT ONTO ONSUREZ RD, FOLLOW 1/2 MILE, TURN RIGHT ONTO BRAMBLE RD. FOLLOW BRAMBLE RD. F/ 1 MILE, STAY STRAIGHT ONTO HARROUN RD. F/ 1.4 MILES. TURN RIGHT ONTO LOCATION RD.. FOLLOW IT .7 MILES To LOCATION.					
Scan Texas	Diamondback Energy	State Neal Lethco 10-9 5WA	Spudded: 5/24/2019	Jon Bruce Trotter	Rocky Broumley
281-605-2133	N 31 4 20 W 102 55 22			Pecos, Co	(Permian-Basin)
From I-20 exit 80 in Monahans go south on TX HWY 18 for 35 miles to Lethco Lane Ranch Road, turn RIGHT and go about 2 miles, turn left and continue 0.7 miles, turn left and go 0.1 miles to location on the left. STRICT MAX SPEED 20 MPH! NO TRASH AND NO SPEEDING!					
Scan Patriot	Rio Oil & Gas (Permian) II,LLC	Conquista State Unit 54-1-8 9H	Spudded: 5/11/2019	John Carroll	Justin Shirey
281-605-2134	N 31 25 21 W -103 31 24	Rig Move		Reeves, Co.	(Permian-Basin)
From the intersection on 302 and 285. Turn left (south) on 285 for 0.6 miles. Turn right (west) onto lease road for 1.1 miles and the location will be on the left. Next Location: From the intersection of HWY 285 and 302 near Mentone Tx. Take 285 North for 18 miles. Turn left off of 285 and onto CR 437. Take 437 3 miles and turn right onto location road. Follow location road for .5 miles to location.					
Scan Liberty	KJ-Energy	Pool-Cyphers-White 1H	Spudded: 5/25/2019	James Manderud	Paxton Lindsey
281-605-2135	N 32 5 36 W -94 37 59			Panola, Co	(Ark-La-Tex)
From Carthage take Hwy 79 toward Henderson, turn left on FM1798. Go 6.3 miles to location road on the right. Turn right on lease road go 1.3 miles stay to the right to the location.					
Scan Star	Diamondback Energy	State Barb 10-5 B 2WA	Spudded : 5/13/2019	Randy Joseph	Wane Fitzgerald
281-605-2136	N 31 19 45 W - 103 13 13			Reeves, Co.	(Permian-Basin)
FROM THE INTERSECTION OF I-20 & HWY 18 (EXIT 80) IN MONAHANS TX, GO SOUTH ON HWY 18 FOR 4.6 MILES. TURN RIGHT ONTO FM 1776 AND CONTINUE SOUTHWEST FOR 17.3 MILES TO FM 1450. GO NORTHWEST TOWARDS PECOS ON FM 1450 FOR 10.3 MILES TO LEASE ROAD ON RIGHT. TURN ONTO LEASE ROAD AND CONTINUE FOR 0.3 MILES. TURN RIGHT AND GO 0.1 MILES TO PAD ON LEFT.					
Scan Endeavor	XTO Energy	Penguins DU B1	Spudded: 5/27/2019	Kenny Fickey	Kyle Sutton
281-605-2139	N 31 26 5 W -94 15 50			San Augustine, Co.	(Ark-La-Tex)
FROM SAN AUGUSTINE, AT INTERSECTION OF HWY 96 & HWY 1277, GO SOUTH ON 1277 APPROXIMATELY 10 MILES TO LEASEROAD ON LEFT. TURN AND FOLLOW TO RIG FROM INTERSECTION OF HWY 103 & 1277 (AT CROSSROADS) GO NORTH ON 1277 FOR 5 MILES TO LEASE ROAD ON RIGHT.TURN AND FOLLOW TO RIG.					
Scan Vision	XTO Energy.	Zant Bridget 2615 2615AH	Spudded: 6/1/2019	Lance Dement	Justin Molandes
281-605-2140	N 31 58 17 W -101 44 34			Glasscock, Co.	(Permian-Basin)
FROM INTERSECTION OF I-20 AND 137 IN STANTON. GO SOUTH ON 137 FOR 12 MILES. TURN LEFT ONTO CR 460, GO 0.4 MILES TO LOCATION					
Scan Quest (NM)	COG Operating, LLC	Boone 16 State Com 4H	Spudded: 5/11/2019	Tony Richardson	Zach Collett
281-605-2141	N 32 28 31 W -103 35 0			Lea,Co.	(Permian-Basin)
From Eunice New Mexico headed towards Hobbs on 176 turn left (stay on 176) go 6.7 miles turn left (stay on 176) go 13.7 miles turn left on lease road, go 3.7 miles turn right at Y go 4.8 miles turn right on lease road go 1 mile stay left at the Y and go 1.3 miles to rig location on right					
Scan Titan	Stacked	Blazer Staked 1	Spudded:	Dewayne Harris	Wise Menah
281-605-2137	N 32 10 18 W -94 19 21	Waiting on next location		Panola. Co	(Ark-La-Tex)
HWY 79/59 IN CARTHAGE TX. @ BLAZER SERVICES YARD STACKED					

Odessa New Yard address: 551 South FM 866, Odessa, TX 79763. Office # 432-332-8084

(From Odessa head west On I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles, yard on East side (right).

Rig Manager on duty is **Highlighted**