

Scan Discoverer		HIGH SKY J 42-43 4309H	Spudded: 12/20/20	Travis Ball	Truitt Thompson
281-746-9653	N 32.0516 W -101.92			MIDLAND, CO.	(Permian Basin)
From Midland take HWY 307 E towards Greenwood for 4.2 miles. Turn Left (North) on CR 1110, drive 1.9 miles. Turn Right, (East) on Lease Road, drive .5 miles to the T. Turn Left, (North) for .2 miles to location. NEXT RIG MOVE: Estimated Move Date: 01/17/21 WALK 25' BACK 75' TO THE 1062H WELL.					
Scan Spirit		Alford JB Birdwell 2H	Spudded: 10/31/20	James Manderud	Eric Blake
281-606-2279	N 32.079 W -94.7504			RUSK, CO.	(Ark-La-Tex)
FROM HWY 79 & 259 IN HENDERSON, TAKE 259 TOWARDS MT ENTERPRISE. GO 3.5 MILES TURN LEFT ON CR 317. GO 1.8 MILES AND TURN RIGHT ON LEASE RD. NEXT RIG MOVE: Walk back to 1H					
Scan Patriot		Diamondback 24-25 FED COM 1BS 4H	Spudded: 1/3/21	Joseph Dover	Justin Shirey
903-205-8399	N 32.6681 W -103.6126			LEA, CO.	(NM) (Permian Basin)
From Hobbs, New Mexico take 180 west of town for 30 miles and turn right onto Smith Ranch Rd. Stay on Smith Ranch Rd. for two miles and turn left onto lease road. Follow lease road for 4.5 miles and turn right. Go .8 miles and turn left. Go 2.7 miles to location road on the left. Follow location road .4 miles to location. NEXT RIG MOVE INFO: ESTIMATED MOVE DATE: 1/28/21 FROM HOBBS, NM TAKE 180 WEST FOR 30 MILES. TURN RIGHT ON SMITH RANCH ROAD. GO 2 MILES AND TURN RIGHT ON LEASE ROAD (BY BIG CIMAREX SIGN). GO 2 MILES AND TAKE A LEFT. GO 1.9 MILES AND STAY TO LEFT. GO 8/10ths OF A MILE ONTO LOCATION.					
Scan Quest		Aftermath West B Unit 302H	Spudded: 12/27/20	Tony Richardson	Keith Davis
281-766-7242	N 31.8472 W -103.342			LOVING, CO.	(Permian Basin)
FROM INTERSECIION OF 302 AND 115 IN KERMIT, GO WEST ON 302 FOR 2.9 MILES, TURN RIGHT ON CR101 (FRYING PAN RD), GO 7.4 MILES, TURN LEFT ON LEASE RD, GO 8.4 MILES, TURN LEFT, GO 4.3 MILES TO LOCATION. (20 MPH SPEED LIMIT STRICTLY ENFORCED). NEXT RIG MOVE INFO: Boomerang D401 and E402 pads, From intersection of 302 and 115 in Kermit, TX take 302 West for 2.9 miles turn right on CR 101 (frying pan road) go 7.4 miles turn left into lease road (white cattle guard P15) go 12.3 miles turn right onto lease road, go 1.3 miles, turn left, go .7 miles to rig on left.					
Scan Legacy		Carolyn 1-2H35X	Spudded: 1/8/21	Paxton Lindsey	Derek Yarbrough
281-606-0182	N 33.8834 W -97.0686			LOVE, CO.	(OKLAHOMA)
From I-35 (Oklahoma) exit 15 (Marietta exit), east hwy 32 for 1.0 miles, then south hwy 77 for 3.0 miles (Caution: School Zone: 25 mph), east Loves Valley Road (McGehee Rd) for 4.2 miles. Location is on south side of road. NEXT RIG MOVE: Estimated Rig Move: Early April, Location TBD.					
Odessa Yard	Office # (432) 332-8084				
From Odessa head west on I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles, yard will be on the East side (right). Don't follow GPS directions, it will take you to another town. 551 South FM 866, Odessa, TX 79763.					
Yukon Yard	Office # (405) 437-0408				

Rig Manager on duty is Highlighted