

Scan Discoverer		BLAGRAVE J 31-43 4210H	Spudded: 3/31/21	Travis Ball	Truitt Thompson
281-746-9653	N 32.4651 W -101.759			MIDLAND, CO.	(Permian Basin)
FROM STANTON TAKE WHY 137 NORTH 14.8 MILES. TURN RIGHT ON FM 846 AND GO 5.0 MILES. TURN LEFT ON FM 3263 AND GO 5.7 MILES TO STOP SIGN. TURN RIGHT ON FM 26 AND GO 2.4 MILES TO LEASE ROAD ON THE LEFT. GO 1 MILE DOWN LEASE ROAD TO RIG. NEXT RIG MOVE: WALK RIG 250 YARDS TO NEXT PAD.					
Scan Spirit		Marsh TD Harrington 1H	Spudded: 2/25/21	James Manderud	Eric Blake
281-606-2279	N 32.628 W -95.0421			UPSHURE, CO.	(Ark-La-Tex)
Big Sandy/Pritchett From intersection of Hwy 80 and Hwy 155 in Big Sandy, turn North on Hwy 155. Drive right 5 miles. Turn right at Mulberry road next to Church. Drive 1/2 mile to location road on right. Sign at entrance says TD Marsh 1. NEXT RIG MOVE: Move to Henderson					
Scan Texas		PINTAIL D 31-30 4204H	Spudded: 3/13/21	Joey Dover	Monty Shultz
903-650-8477	N 31.9015 W -101.9214			MIDLAND, CO.	(Permian-Basin)
From intersection of I-20 and SH 158 east of Midland, take 158 toward Garden City for 6.6 miles. Turn right on county road 1110 go 3.5 miles. Turn right on lease road and go 0.5 miles to location on right. If traveling west (from Big Springs) take exit 138 off I-20. If traveling east (from Midland) take exit 137B off I-20. NEXT RIG MOVE: Walk 25'					
Scan Patriot		STETSON 13-24 FED COM 1BS 6H	Spudded: 3/14/21	Mitchell Clemens	Justin Molandes
903-205-8399	N 32.6678 W -103.6123			LEA, CO.	(NM) (Permian Basin)
FROM HOBBS, NM TAKE 180 WEST FOR 30 MILES. TURN RIGHT ON SMITH RANCH ROAD. GO 2 MILES AND TURN RIGHT ON LEASE ROAD (BY BIG CIMAREX SIGN). GO 2 MILES AND TAKE A LEFT. GO 1.9 MILES AND STAY TO LEFT. GO 8/10ths OF A MILE ONTO LOCATION. NEXT RIG MOVE: From intersection of Hwy 176 & Hwy 180 go south on Hwy 176 for 6.4 miles. Turn right (south) on location road. Go .6 miles to y in road stay to left and continue 1.8 miles to location.					
Scan Quest		Boomerang G #403H	Spudded: 4/1/21	Tony Richardson	Keith Davis
281-766-7242	N 31.8839 W -103.453			LOVING, CO.	(Permian Basin)
From intersection of 302 and 115 in Kermit, TX take 302 West for 2.9 miles, turn right on CR 101 (frying pan road) go 7.4 miles turn left into lease road (white cattle guard) go 13 miles turn right onto lease road go 2.4 cross cattle guard, turn left go .7 miles to rig. NEXT RIG MOVE: Echo B Unit #2203H and #2204H Driving directions- From 302 and 115 just West of Kermit, Go West on 302 for 3 miles, Turn Right (North), onto CR 101, go 7.4 miles to P1 lease Turn Left (West), go 7.0 miles, Turn Right (North) go 4.4 miles, Turn Right (East) 0.3 miles, Turn Right (South) go 0.3 miles to location.					
Scan Titan		STEVIE RAY E UNIT #2 LS	Spudded: 4/4/21	Travis Richardson	Jeramie Dickens
903-650-8486	N 32.4631 W -101.8316			Martin, CO.	(Permian Basin)
FROM I-20 AND HWY 137 IN STANTON, EXIT 156 AND GO NORTH ON 137 FOR 15 MILES, TURN RIGHT ON 846 GO EAST 5 MILES, TURN LEFT ON HWY-3263 GO 5.5 MILES NORTH, TURN LEFT AND CONTINUE NORTH ON HWY 26 FOR 1.7 MILES TO CR-4400. TURN LEFT ON 4400 GO WEST 1.5 M. to lease road. NEXT RIG MOVE: Walk 25' West.					
Scan Legacy		Carolyn 1-2H35X	Spudded: 1/8/21	Paxton Lindsey	Derek Yarbrough
281-606-0182	N 33.8834 W -97.0686			LOVE, CO.	(OKLAHOMA)
From I-35 (Oklahoma) exit 15 (Marietta exit), east hwy 32 for 1.0 miles, then south hwy 77 for 3.0 miles (Caution: School Zone: 25 mph), east Loves Valley Road (McGehee Rd) for 4.2 miles. Location is on south side of road. NEXT RIG MOVE: WALK BACK 40' AND FINISH TARA WELL.					
Odessa Yard	Office # (432) 332-8084				
From Odessa: Head west on I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles, yard is on the East side (right). Don't follow GPS directions, it will take you to another town. 551 South FM 866, Odessa, TX 79763.					
Yukon Yard	Office # (405) 437-0408				

Rig Manager on duty is **Highlighted**